HABS WVA, 35-WHEEL, 34-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Christian Hess House 811 Main Street Wheeling Ohio County West Virginia HABS No. WV-207

Jack E. Bo	oucher, Photographer March 1977
WV-207-1	EAST FRONT
WV-207-2	FRONT ENTRANCE AND FIRST-FLOOR WINDOWS
WV-207-3	CAST-IRON FRONT FIRST-FLOOR BALCONY
WV-207-4	FRONT (EAST) ROOM THROUGH ARCHWAY WITH SLIDING DOORS
WV-207-5	FRONT ROOM
WV-207-6	DETAIL OF FRONT ROOM CHIMNEY WALL
WV-207-7	FRONT ROOM MANTELPIECE
WV-207-8	DETAIL OF CEILING CORNER AND WINDOW CORNICE
WV-207-9	ELECTRIC CEILING FIXTURE IN WEST ROOM
WV-207-10	FRONT HALL, LOOKING EAST TOWARD FRONT DOOR
WV-207-11	LINCRUSTA WAINSCOT IN FRONT HALL
WV-207 - 12	STAINED GLASS OF FRONT DOORS AND TRANSOM
WV-207-13	STAINED GLASS IN FRONT DOORS
WV-207-14	STAINED GLASS DOOR PANEL
WV-207-15	DETAIL OF STAINED GLASS PANEL
WV-207-16	ORIGINAL WALLPAPER AND LINCRUSTA DADO, SECOND FLOOR
wv-207-17	ETCHED GLASS DOOR PANEL

HABS WVA 35-WHEEL, 34-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

ADDENDUM TO:

HABS No. WV-207 (pg. 2)

CHRISTIAN HESS HOUSE 811 Main Street Wheeling Ohio County West Virginia

WV-207-1 through WV-207-17 were previously transmitted to the Library of Congress.

INDEX TO COLOR TRANSPARENCIES

All color xeroxes were made from a duplicate color transparency.

Jack Boucher, Photographer, March 1977

WV-207-18 (CT)	ELECTRIC CEILING FIXTURE IN WEST ROOM
WV-207-19 (CT)	ELECTRIC CEILING FIXTURE IN WEST ROOM
WV-207-20 (CT)	STAINED GLASS IN FRONT DOOR
WV-207-21 (CT)	STAINED GLASS DOOR PANEL
WV-207-22 (CT)	DETAIL OF STAINED GLASS DOOR PANEL

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS WV-207

ADDENDUM TO: CHRISTIAN HESS HOUSE 811 Main Street Wheeling Ohio County West Virginia

INDEX TO COLOR TRANSPARENCIES

Jack E. Boucher, photographer,

WV-207-23 (CT) View looking to the east (front) elevation (duplicate of HABS No. WV-207-1)